

**Investigation of Polychlorinated Biphenyl
Contamination in the
West Branch of the Housatonic River
Pittsfield, Massachusetts**

Prepared by:

**Massachusetts Department of Environmental Protection
Western Regional Office
Bureau of Waste Site Cleanup
436 Dwight Street
Springfield, Massachusetts 01103**

January 2005

TABLE OF CONTENTS

	<u>Page</u>
SUMMARY	1
HISTORY OF PREVIOUS REMEDIAL INVESTIGATIONS ALONG THE WEST BRANCH OF THE HOUSATONIC RIVER	1
DEPARTMENTAL INVESTIGATIONS	3
Sediment Sampling	3
<i>Sediment Sampling at Dorothy Amos Park</i>	3
<i>Sediment Sampling Downstream of Dorothy Amos Park</i>	4
<i>Sediment Sampling North of Dorothy Amos Park</i>	5
Riverbank Soil Sampling	5
<i>Riverbank Soil Sampling at Dorothy Amos Park</i>	5
<i>Riverbank Soil Sampling Downstream of Dorothy Amos Park</i>	6
Soil Borings and Groundwater Monitoring Wells	6
<i>Soil Borings at Dorothy Amos Park</i>	6
<i>Groundwater Monitoring Wells at Dorothy Amos Park</i>	6
DEPARTMENTAL SAMPLING RESULTS	7
Sediment Sampling Results	7
<i>Sediments at Dorothy Amos Park (transects T 00150 through T 00700)</i>	7
<i>Sediments North and South of Dorothy Amos Park (transects T 00000N, T 00000 through T 00150, and T 01100 through T 10300)</i>	7
<i>Sediments at Potential Exposure Areas</i>	8
Riverbank Soil Sampling Results	8
<i>Riverbank Soils at Dorothy Amos Park (transects T 00150 through T 00700)</i>	8

<i>Riverbank Soils North of the Park (transects T 00000 through T 00100)</i>	8
<i>Riverbank Soils at Potential Exposure Areas</i>	8
Soil Borings and Groundwater Sampling Results	9
<i>Soil Borings at Dorothy Amos Park</i>	9
<i>Groundwater Samples at Dorothy Amos Park</i>	9
Data Validation	9
DEP'S RECOMMENDATIONS	10

FIGURES

- Figure 1:** West Branch Housatonic River – Locations of Sediment/Bank Sampling Transects & Soil Borings/Monitoring Wells at Dorothy Amos Park
- Figure 2:** West Branch Housatonic River – Locations of Sediment Sampling Transects and Potential Exposure Areas

TABLES

- Table 1:** West Branch Housatonic River - Sediment Sampling Results – PCBs
- Table 2:** West Branch Housatonic River - Riverbank Sampling Results – PCBs
- Table 3:** Results for Soil Borings at Dorothy Amos Park and Additional Riverbank Sample at Transect T 00300 – VOCs, SVOCs, PCBs and Metals
- Table 4:** Results for Groundwater Sampling at Dorothy Amos Park – PCBs
- Table 5:** Average PCB Concentrations in West Branch Housatonic River Sediments
- Table 6:** Average PCB Concentrations in Exposure Areas between West Housatonic Street and South Street
- Table 7:** Average PCB Concentrations in West Branch Housatonic Riverbank Soils